

# Certificate of Registration

## ENVIRONMENTAL MANAGEMENT SYSTEM - ISO 14001:2015

This is to certify that:

Total Drain Group Pty Ltd  
T/A TDG Environmental  
T/A Mainstream Recycling  
100 - 104 Agar Drive  
Truganina VIC 3029

Holds Certificate Number:

**EMS 540521**

and operates an Environmental Management System which complies with the requirements of ISO 14001:2015 for the following scope:

For drain cleaning with vacuum recovery services, non-destructive digging and CCTV pipe inspection and repairs.  
For the recycling and treatment of solid and liquid soil and slurry waste.

For and on behalf of BSI:



Michael Lam, Managing Director Assurance - APAC

Original Registration Date: 2008-11-19

Latest Revision Date: 2023-09-22

Effective Date: 2023-11-20

Expiry Date: 2026-11-19

Page: 1 of 3



...making excellence a habit.™

This certificate was issued electronically and remains the property of BSI Group ANZ Pty Limited, ACN 078 659 211 and is bound by the conditions of contract. This certificate can be verified at [www.bsi-global.com/clientdirectory](http://www.bsi-global.com/clientdirectory). Printed copies can be validated at [www.bsi-global.com/ClientDirectory](http://www.bsi-global.com/ClientDirectory). Further clarifications regarding the scope of this certificate and the applicability of ISO 14001:2015 requirements may be obtained by consulting the organization. This certificate is valid only if provided original copies are in complete set.

Information and Contact: BSI, Kitemark Court, Davy Avenue, Knowlhill, Milton Keynes MK5 8PP. Tel: + 44 345 080 9000  
BSI Assurance UK Limited, registered in England under number 7805321 at 389 Chiswick High Road, London W4 4AL, UK.  
Information and Contact: BSI Group ANZ Pty Limited, ACN 078 659 211: Suite 1, Level 1, 54 Waterloo Road, Macquarie Park, NSW 2113  
A Member of the BSI Group of Companies.

Certificate No: **EMS 540521**

Location	Registered Activities
Total Drain Group Pty Ltd t/a TDG Environmental t/a Mainstream Recycling 6 Sleigh Place Wetherill Park NSW 2164	For drain cleaning with vacuum recovery services, non-destructive digging and CCTV pipe inspection and repairs. For the recycling and treatment of solid and liquid soil and slurry waste.
Total Drain Group Pty Ltd t/a TDG Environmental 1A, 84 Ingleston Road Wakerley QLD 4154	For drain cleaning with vacuum recovery services, non-destructive digging and CCTV pipe inspection and repairs. For the recycling and treatment of solid and liquid soil and slurry waste.
Total Drain Group Pty Ltd T/A TDG Environmental 6 Haworth Court Breakwater VIC 3129	For the recycling and treatment of solid and liquid soil and slurry waste.
Total Drain Group Pty Ltd T/A TDG Environmental 994 Wellington Street Strathfieldsaye VIC 3551	For drain cleaning with vacuum recovery services, non-destructive digging, CCTV inspection and pipe repairs.
Total Drain Group Pty Ltd T/A TDG Environmental 10 Bancroft Crescent Glendene, Waitakere AKL 0602 New Zealand	For drain cleaning with vacuum recovery services, non-destructive digging, CCTV inspection, pipe repairs. For the recycling and treatment of solid and liquid soil and slurry waste.
Total Drain Group Pty Ltd t/a Mainstream Recycling 7-8 Haworth Court Breakwater VIC 3129	For drain cleaning with vacuum recovery services, non-destructive digging and CCTV pipe inspection and repairs. For the recycling and treatment of solid and liquid soil and slurry waste.
Total Drain Group Pty Ltd T/A TDG Environmental 4 Stone Street Kaiapoi, Christchurch 7630 New Zealand	For drain cleaning with vacuum recovery services, non-destructive digging, CCTV inspection and pipe repairs.
Total Drain Group Pty Ltd T/A TDG Environmental 5 Winston Place Henderson, Auckland City 0610 New Zealand	For drain cleaning with vacuum recovery services, non-destructive digging, CCTV inspection and pipe repairs.

Original Registration Date: 2008-11-19

Latest Revision Date: 2023-09-22

Effective Date: 2023-11-20

Expiry Date: 2026-11-19

Page: 2 of 3

This certificate was issued electronically and remains the property of BSI Group ANZ Pty Limited, ACN 078 659 211 and is bound by the conditions of contract. This certificate can be verified at [www.bsi-global.com/clientdirectory](http://www.bsi-global.com/clientdirectory). Printed copies can be validated at [www.bsi-global.com/ClientDirectory](http://www.bsi-global.com/ClientDirectory). Further clarifications regarding the scope of this certificate and the applicability of ISO 14001:2015 requirements may be obtained by consulting the organization. This certificate is valid only if provided original copies are in complete set.

Information and Contact: BSI, Kitemark Court, Davy Avenue, Knowlhill, Milton Keynes MK5 8PP. Tel: + 44 345 080 9000  
BSI Assurance UK Limited, registered in England under number 7805321 at 389 Chiswick High Road, London W4 4AL, UK.  
Information and Contact: BSI Group ANZ Pty Limited, ACN 078 659 211: Suite 1, Level 1, 54 Waterloo Road, Macquarie Park, NSW 2113  
A Member of the BSI Group of Companies.

Certificate No: **EMS 540521**

Location	Registered Activities
Total Drain Group Pty Ltd T/A TDG Environmental 32-34 Gravel Pits Road South Geelong VIC 3220	For drain cleaning with vacuum recovery services, non-destructive digging, CCTV inspection and pipe repairs.
Total Drain Group Pty Ltd T/A TDG Environmental 2 Nell Place Whangarei 0110 New Zealand	For drain cleaning with vacuum recovery services, non-destructive digging, CCTV inspection and pipe repairs.
Total Drain Group Pty Ltd T/A TDG Environmental 21 Waiu St Wainuiomata, Lower Hutt 5014 New Zealand	For drain cleaning with vacuum recovery services, non-destructive digging, CCTV inspection and pipe repairs.
Total Drain Group Pty Ltd T/A TDG Environmental 16/18 Nicholas Dr Dandenong South 3175	For drain cleaning with vacuum recovery services, non-destructive digging, CCTV inspection and pipe repairs.
Total Drain Group Pty Ltd T/A TDG Environmental T/A Mainstream Recycling 100 - 104 Agar Drive Truganina VIC 3029	For drain cleaning with vacuum recovery services, non-destructive digging and CCTV pipe inspection and repairs. For the recycling and treatment of solid and liquid soil and slurry waste.
Total Drain Group Pty Ltd T/A TDG Environmental 6 Sherriffs Rd Lonsdale SA 5160	For drain cleaning with vacuum recovery services, non-destructive digging, CCTV inspection and pipe repairs.
Total Drain Group Pty Ltd T/A TDG Environmental 103 Cowpasture Rd Wetherill Park NSW 2164	For drain cleaning with vacuum recovery services, non-destructive digging and CCTV pipe inspection and repairs.
Total Drain Group Pty Ltd T/A TDG Environmental 89 Cowpasture Rd Wetherill Park NSW 2164	For drain cleaning with vacuum recovery services, non-destructive digging, CCTV inspection and pipe repairs.

Original Registration Date: 2008-11-19

Latest Revision Date: 2023-09-22

Effective Date: 2023-11-20

Expiry Date: 2026-11-19

Page: 3 of 3

This certificate was issued electronically and remains the property of BSI Group ANZ Pty Limited, ACN 078 659 211 and is bound by the conditions of contract. This certificate can be verified at [www.bsi-global.com/clientdirectory](http://www.bsi-global.com/clientdirectory). Printed copies can be validated at [www.bsi-global.com/ClientDirectory](http://www.bsi-global.com/ClientDirectory). Further clarifications regarding the scope of this certificate and the applicability of ISO 14001:2015 requirements may be obtained by consulting the organization. This certificate is valid only if provided original copies are in complete set.

Information and Contact: BSI, Kitemark Court, Davy Avenue, Knowlhill, Milton Keynes MK5 8PP. Tel: + 44 345 080 9000  
BSI Assurance UK Limited, registered in England under number 7805321 at 389 Chiswick High Road, London W4 4AL, UK.  
Information and Contact: BSI Group ANZ Pty Limited, ACN 078 659 211: Suite 1, Level 1, 54 Waterloo Road, Macquarie Park, NSW 2113  
A Member of the BSI Group of Companies.